



Slag Cement (Southern) Sdn Bhd

(Company No. 267497-W)

(A YTL COMPANY)

Lot 3 OFF JALAN PUKAL, 81707 PASIR GUDANG, JOHOR DARUL TAKZIM
TEL: 07-2525355 FAX: 07-2521263 e-mail: wksek.pcsb@ytl.com.my

Basehub Multi Solutions PLT
14, Jalan Bakawali 37,
Taman Johor Jaya,
81100 Johor Bahru,

18/11/2014

Dear Sir,

It is hereby confirm that Orion 288, Seal Saver was giving effectiveness to the Gear Box at :-

- i) Reject Belt Bucket Elevator
- ii) Transport Belt Bucket Elevator

We have leaking problem on the Gear Box's Seal. And after using Orion 288 within 2 weeks, there is no more leaking.

We are very confident with this product.

Your Sincerely,

6th Floor
Yeoh Tiong Lay Plaza
55 Jalan Bukit Bintang
55100 Kuala Lumpur
Tel: 03-2117 0088
2142 3300, 2142 6633
Fax: 03-2144 3062
E-mail: ctrl@ytl.com.my

Website :
www.ytlcommunity.com

8th Floor
Menara ING
84 Jalan Raja Chulan
50200 Kuala Lumpur
Tel: 03-2166 0800
Fax: 03-2166 9588

(Snr. Prod. & Maint. Exec)
AHMAD KAMAR BIN DARMAN



(Plant Manager)
VIJAYA KUMAR A/L REGANSAMI

VIJAYA KUMAR A/L RENGASAMY
PLANT MANAGER
SLAG CEMENT (SOUTHERN) SDN. BHD.